

---

## Update information

---

We recommend that you always use the latest firmware version available for the unit. For information about the latest firmware, visit the TEAC Global Site (<http://teac-global.com/>).

---

\*\*\* Beware of the following when updating \*\*\*

- Be careful not to let the power be interrupted during the update.
  - Do not load or remove media while updating.
  - If the power is interrupted or media is loaded or removed during the update, the unit might become unstartable.
- 

## Maintenance items

---

### V1.02 fix

- In V1.01, the modification dates and times of already recorded files (wav) on a microSD card would be updated erroneously when the card was loaded. This has been fixed.

\*\*\* NOTE \*\*\*

This issue only occurred with V1.01. It did not occur with any other versions.

---

### V1.01 fix

- Compatibility with music and video editing software has been improved for audio files handled by this unit.
  - If the power shut down during the recording of files, those files could not be properly loaded by some audio and video editing software. This has been improved.
  - An issue that would on rare occasions caused noise to be recorded at the end of files when set to 24-bit has been improved.
  - The remaining recording time for cards is now shown correctly when the dual recording function is on.
  - Operation stability has been improved.
-