

TASCAM
TEAC Professional Division

US-2000
USB Audio Interface

Release Notes

Information on: Driver v2.0, Firmware v1.01

US-2000 Release Notes

General information on updates

Always ensure that you are running the latest US-2000 driver software and firmware by visiting www.tascam.com or www.tascam.de

Driver Release Notes

IMPORTANT

You must uninstall the old driver before installing a new driver.

See chapter “3 – Installation” of the US-2000 Owner’s Manual for how to install and uninstall the driver.

If a firmware update has been released together with a new driver, install the new driver first before installing the firmware.

New features with version 2.0 for Mac OS X

This version adds support for the 32-bit versions of Mac OS X 10.5.8 and 10.6 (Snow Leopard). 64-bit kernel mode is not supported.

IMPORTANT

In order to use the US-2000 on Mac OS X 10.3.9 or 10.4.11, you must use the drivers from the original CD.

Known issues with version 2.0 for Mac OS X

After rebooting from Sleep mode, an audio application may not recognize the US-2000 connected via USB.

Firmware Release Notes

Maintenance items in v1.01

The US-2000 might generate periodic noise from its Line and Headphone outputs when the digital output on the US-2000's Control Panel is changed from 1/2 to 3/4 several times at high sampling frequency while connected to a Macintosh computer. This has been corrected.

Updating the firmware

- 1 Install the latest US-2000 driver on your Windows or Macintosh computer.**
- 2 Make sure that the US-2000 is connected to your computer via a USB cable.**
- 3 Run the firmware updater file (Windows or Mac version).**

When the US-2000 is recognized, a screen appears.

- 4 Click the *write firmware* button.**

When the update process is complete, the following message appears: *Update to version xx successful.*

- 5 Disconnect the USB cable from the US-2000.**

The main updater screen is shown again.

- 6 Click the *Exit* button to close the updater.**

TASCAM

TEAC Professional Division

US-2000

TEAC CORPORATION

Phone: +81-42-356-9143
1-47 Ochiai, Tama-shi, Tokyo 206-8530, Japan

www.tascam.com

TEAC AMERICA, INC.

Phone: +1-323-726-0303
7733 Telegraph Road, Montebello, California 90640, USA

www.tascam.com

TEAC CANADA LTD.

Phone: +1905-890-8008 Facsimile: +1905-890-9888
5939 Wallace Street, Mississauga, Ontario L4Z 1Z8, Canada

www.tascam.com

TEAC MEXICO, S.A. de C.V.

Phone: +52-55-5010-6000
Río Churubusco 364, Colonia Del Carmen, Delegación Coyoacán, CP 04100, México DF, México

www.tascam.com

TEAC UK LIMITED

Phone: +44-8451-302511
Suites 19 & 20, Building 6, Croxley Green Business Park, Hatters Lane, Watford, Hertfordshire, WD18 8TE, UK

www.tascam.co.uk

TEAC Europe GmbH

Phone: +49 (0) 611-71580
Bahnstraße 12, 65205 Wiesbaden-Erbenheim, Germany

www.tascam.de