
Most recent information

The most recent versions of the software/firmware for this unit are as follows.

Windows

Software	:V2.11 (Previously 2.10. Updated at this time)
Firmware	:V1.01 (Previously 1.01. Not Updated at this time)

Mac OS

Software	:V2.00 (Previously 2.00. Not Updated at this time)
Firmware	:V1.01 (Previously 1.01. Not Updated at this time)

We request that you always use the latest software/firmware version for this unit.
For information about the latest software/firmware, check the TEAC Global Site (<http://teac-global.com/>)

<< New functions >>

Additions in version 2.1 (2017.06.30)

-Now, when a US-2x2/US-4x4 is connected to a Windows computer by USB, the sound device settings will be made automatically and the Settings Panel will launch. (Windows version)

Additions in version 2.00 (2016.11.09)

- The Settings Panel has been altered to make it easier to use. Making settings according to applications by just pressing a button is now possible. In addition, custom settings can now be saved and used. (Windows version)
 - A new software/firmware notification function has been added. When a new version is available, updating to it is possible by just clicking, "Update now" in a pop-up menu.
 - A link to the TASCAM website has been added to the Help menu.
-

Additions in version 1.30 (2016.07.01)

- <Mic Monitor> checkbox has been added to the Mixer panel. If this check is removed, sounds from mics input through IN 1 and IN 2 will not be sent to the headphone output. These input sounds will be mixed with the <PC Audio Out> signal and looped back to the computer.
 - In order to provide compatibility with major communication applications in China, the Windows Playback/Recording devices have been extended. Usually, you can set "Mixing Driver 1 for US-2x2 & US-4x4" as the "Default Device" without a problem. If you do not want "Mixing Driver 2 for US-2x2 & US-4x4" to appear, right-click it, select "Disabled" from the menu that appears, and remove the check next to "Show Disabled Devices".
-

Additions in version 1.20 (2016.03.29)

- An automatic sample rate setting function has been added. (When you change the "Sample Rate" item on the Software Mixer panel, this is reflected by the sample rate in the Windows Sound settings.)
 - The "External Effects (ASIO) " item can now be changed even when in DAW mode in order to allow use with Skype and other audio communication tools.
-
-

Additions in version 1.10 (2016.03.02)

- Mono output or stereo output can be selected for WDM in order to support a greater variety of distribution software.
- The BROADCAST/KARAOKE mode setting used before switching to DAW mode is now retained.

Version 1.00 1st Release. (2016.01.29)

<< Maintenance items >>

Fix in version 2.11 (2018.03.19)

- The sound device settings(Windows) and the sampling rate set in the DAW software were not always reflected in the Settings Panel. This has been fixed.
- Operation stability has been improved.

Fix in version 2.10 (2017.06.30)

- Operation stability has been improved.

Fix in version 2.02 (2017.03.01)

- A problem with the various settings from the time that the unit was previously turned off not loading properly when starting Windows has been fixed.

Fix in version 2.01 (2016.12.22)

- When turn on or restart a computer under Windows 10 64bit while the US-2x2/US-4x4 are being connected, the drivers were not able to be verified in some cases. This technical issue has been fixed.
- Operation stability has been improved.

Fix in version 2.00 (2016.11.9)

- Operation stability has been improved.

Fix in version 1.30 (2016.07.01)

- Operation stability has been improved.

Fix in version 1.20 (2016.03.29)

- Operation stability has been improved.

Fix in version 1.10 (2016.03.02)

- Installation of the driver and Software Mixer has been combined so the unit can be used sooner.
- Audio could be delayed depending on the computer system. This is been fixed.
- Operation stability has been improved.

Version 1.00 1st Release. (2016.01.29)