

TASCAM

US-428 Windows Driver Release Notes

Version 3.40 – October 16, 2007

Supported Operating Systems

Windows driver version 3.40 supports:

- 32-bit Windows XP Service Pack 2
- 64-bit Windows XP Service Pack 2
- 32-bit Windows Vista
- 64-bit Windows Vista

Always ensure that you are running the latest driver software and firmware by visiting <http://www.tascam.com>

New Features in 3.40

- Support for Windows Vista has been added.

Known Issues in 3.40

- On 64-bit Windows, the US-428's Select buttons and EQ controls do not work with SONAR.